

STRUCTURE NO. 00708

PONUS RIDGE ROAD

over

ROUTE 15

NEW CANAAN

(In depth)
Supplemental / Special Inspection
on
11/25/2011

Inspected by Other - 17
for Area 6

TEAM:	Forwarded to TE3 Ron Jantzen	Date	12/28/2011
TE3:	Reviewed by TE3 Ron Jantzen	Date	12/28/2011
	BMM Required	No	
	Town Bridge	No	
	Rating <= 5 (Items 58,59,60 or 62)	Yes	
	Rating Change 2 or More Values	No	
	Forwarded to Supervisor Sandra Dumas	Date	12/28/2011
	Forwarded to "To Be Copied Drawer" <input type="checkbox"/>	Date	
	Date BRI-19 Entered	12/28/2011	
SUPERVISOR:	Reviewed by Supervisor SDumas	Date	1/22/12
SUPPORT:	Date Copies Made 2/15/12	BMM No	trans
	Scanned By: Pnd	Date Scanned 2/15/12	PDF Box No

NBI: Yes

Structure No.	00708	Town	New Canaan
Inspection Date	11/25/2011	Inspectors	R Jantzen

TABLE OF CONTENTS

Loose Forms (not bound in report)

Number of
Sheets Enclosed

Maintenance Memo		
Flagging Memos		
PONTIS Element Data Collection Form		
Plan Sheets	Already on File <input checked="" type="checkbox"/>	

Bound Report Pages

Title Cover Sheet		1
Table of Contents		1
Executive Summary		
Field Notes		8
Calculations:	Load Rating Evaluation	
	Quantities & Cost Estimate	
Photo Sheets		18
Photo Images		36

Forms

BRI-18 Bridge Inspection Report Form		12
BRI-19 Highway Bridge Inventory Form		2
BRI-25 Highway Bridge Under Entry Form		1

Comments:

Photos are in set of 30 (15 pages) and a set of 6 (3 pages) from a follow-up day. Field notes include 6 pages of sketches and 2 pages on estimated ADT.

00708

Bridge Number

Inspected By: R. Vantrean &

Sufficiency Rating 75.80

Previous Inspection Date 7/12/2010

BS&E Received ☐ Data Entry By: RDSCopies Made ☐ Data Entry Date: 12/23/2011

IDENTIFICATION

Bridge Name

Town Name NEW CANAAN

Inventory Route:

A) Record Type 1

B) Signing Prefix 5

C) Level of Service 0

D) Feature Intersected

E) Directional Suffix 0

F) None of the bel

G) ROUTE 15

H) Facility Carried:

I) Location

J) Milepoint

K) Latitude

L) Longitude

M) Border Bridge:

N) State Code

O) Border Town Name

P) Border Bridge Structure No

Q) Structure Type, Main:

R) Material 1 Concrete

S) Structure Type, Approach:

T) Material 0 Other

U) Number of Spans, Main Unit

V) Number of Approach Spans

W) Deck Structure Type

X) Wearing Surface/Protective System:

Y) Type of Wearing Surface

Z) Type of Membrane

AA) Type of Deck Protection

STATE OF CONNECTICUT

DEPARTMENT OF TRANSPORTATION

BRIDGE SAFETY & EVALUATION

STRUCTURE EVALUATION

SHEET 1 OF 2 FORM BRI-19 REV 10/00

SHEET 1 OF 41

Supplemental

90) Inspection Date	Inspection Team	91) Frequency Class:
2/5/11	g	24 01
Indepth Insp	Deck Survey	Access
2/3/2004	11/25/11	11/1/2000
Fracture:	Type	Frequency
Uwater:	Team	Date
Special:		

CRITICAL FEATURE INSPECTIONS

Type

Frequency

Team

Date

AGE AND SERVICE

106) Year Reconstructed

1 HIGHWAY

B) Under

B) Under

2786

3%

2009

2miles

Half ADT?:

No

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

2011

GEOMETRIC DATA

65ft

65ft

1.1ft

30.0ft

35.5ft

23ft

0 No Median

2298 sqft

14deg

0

99in

30.0ft

0ft

99in

H Ref

12ft

H Ref

3.0ft

1.8ft

BRIDGE COMMENTS

Project No. 0135-0270: Proposed Resurf/Safety Improvements CT 15 Stamford to New Canaan.

Item 29 & Item 30 - Estimated ADT for 2006 (last estimated ADT of 1900 dated 1988). rdj 9/15/06

Route 15 is posted at all entrance ramps for vertical and weight restrictions to maintain "Parkway" appearance. (JCK)

Item 29 & Item 30 - Est. ADT for 2011 (last estimated ADT of 2700 dated 2008)

from New Canaan ADT map) RDT 12/28/11

Item 49 & 52 verified in field in 2011 RDT 12/28/11

12/28/11

CLASSIFICATION

112) NBIS Bridge Length	Yes	
104) Highway System	0	Off System
26) Functional Class	16	Urban Minor Arterial
100) Defense Highway	0	Route is not a STRAHNET Route
101) Parallel Structure	N	No parallel structure exists
102) Direction of Traffic	2	2-way traffic
103) Temporary Structure		
110) Designated National Network	0	Not on national network
20) Toll	3	On Free Road
21) Maintain	1	State Highway Agency
22) Owner	1	State Highway Agency
Report Class	S	STATE
37) Historical Significance	1	On National Register

WATERWAY

DrainageBasinCode	
38) Navigation Control	
39) Navigation Vert Clr.	
116) Vert-Lift Brg Nav Min	
111) Pier Abutment Protection	
40) Navigation Horiz Clr.	

PROPOSED IMPROVEMENTS

75A) Type of Work Proposed	
75B) Work Done By	
76) Length of Struct. Improvement	ft
94) Bridge Improvement Cost	\$
95) Roadway Improvement Cost	\$
96) Total Project Cost	\$
97) Year of Improvement Cost Est.	
114) Future ADT	
115) Year Future ADT	1/16/2013

POSTED SIGNS & UTILITIES

Other Posted Signs 1	0	Blank
Other Posted Signs 2	0	Blank
Actual P.L. Single Unit Truck	tons	
Rec. P.L. Single Unit Truck	tons	
Actual P.L. Semi-Trailer Truck	tons	
Rec. P.L. Semi-Trailer Truck	tons	
Rec. P.L. All Vehicles	tons	
Posted Vert Clearance On Bridge	ft	
Posted Vert Under Clearance	ft	
Posted Speed Limit	25	mph

STRUCTURE EVALUATION

SHEET 2 OF 2 FORM BRI-19 REV 10/00

SHEET 2 OF 41

Bridge Number	00708	NBIS Length	
Town Name	NEW CANAAN	Yes '65	
Facility Carried	PONUS RIDGE ROAD		
Feature Crossed	ROUTE 15		

Inspected By: R Jantzen &

LOAD RATING AND POSTING

31) Design Load	4	Evaluation Code	L
63) Operating Rating Type	1	Year of Evaluation	2002
64) Operating Rating	149.7	70) Bridge Posting	5
65) Inventory Rating Type	1	41) Structure Status	A
66) Inventory Rating	89.8		

CONDITION

58) Deck	N	Rating	By
59) Superstructure	5		
60) Substructure	7		
61) Channel & Chan. Protection	N		
62) Culverts	N		

APPRAISALS

67) Structure Evaluation	4	Rating	By
68) Deck Geometry	4		
69) Under Clear Vert & Horiz	2		
71) Waterway Adequacy	N		
72) Approach Rdwy Alignment	6		
113) Scour Critical			

Items 58 Thru 72 Checked By:

36) Traffic Safety Features:

A) Bridge Railings	0
B) Transitions	0
C) Approach Guardrail	0
D) Approach Guardrail End	0

OTHER FEATURES

Fence Required	Yes
Fence Present	No
Fence Height	0.0 ft
Fence Type	
Fence Material	
Fence Top Type	
Barrel Ladder	
Stand Pipes	
Cat Walks	
Movable Inspection System	
Loose Concrete Checked?	

INSPECTION COMMENTS

Proposed Next Indepth Insp Year	2014
Senior	Parviz Mirzaee
Supervisor	Theodore Lapierr

REVIEWED BY: R Jantzen Date 12/28/2011

BRIDGE NUMBER	TOWN NAME	NBIS BRG LGTH
00708	NEW CANAAN	True 65
FACILITY CARRIED	FEATURE CROSSED	
PONUS RIDGE ROAD	ROUTE 15	

INSPECTED BY: R Jantzen

REVIEWED BY: _____ DATE: _____

STATE OF CONNECTICUT
DEPARTMENT OF TRANSPORTATION
DIVISION OF BRIDGE SAFETY EVALUATION

**INVENTORY ROUTE
UNDER STRUCTURE EVALUATION**

FORM BRI-25 REV 10/00

SHEET 3 OF 41 (INSP. REPORT)

<p>DESCRIPTION:</p> <p>5) INVENTORY ROUTE:</p> <p>A) RECORD TYPE <u>2</u></p> <p>B) ROUTE SIGNING PREFIX <u>3</u></p> <p>C) DESIGNATED LEVEL OF SERVICE <u>1</u></p> <p>D) ROUTE NO <u>00015</u></p> <p>11) MILE POINT (INV RTE) <u>12.29</u></p>	<p>IDENTIFICATION</p> <p>Route 15 is posted at all entrance ramps for vertical and weight restrictions to maintain "Parkway"</p> <p>State Highway</p> <p>Mainline</p>	<p>CLASSIFICATION</p> <p>26) INV. RTE. FUNCT CLASSIFICATION <u>12</u> Urban Principal Arterial - <input type="checkbox"/></p> <p>100) DEFENSE HIGHWAY DESIGNATION <u>0</u> Route is not a STRAHNE <input type="checkbox"/></p> <p>** 102) DIRECTION OF TRAFFIC <u>2</u> 2-way traffic <input type="checkbox"/></p> <p>104) HIGHWAY SYSTEM OF INV. ROUTE <u>1</u> On System <input type="checkbox"/></p> <p>110) DESIGNATED NATIONAL NETWORK <u>1</u> On national network <input type="checkbox"/></p>
---	---	---

<p>AGE & SERVICE</p> <p>28B) NUMBER OF INV. ROUTE LANES <u>4</u></p> <p>29) ADT (INV. RTE) <u>66000</u></p> <p>109) TRUCK ADT % (INV. RTE) <u>1</u></p> <p>30) YEAR OF ADT (INV. RTE) <u>2009</u></p> <p>41) INV ROUTE OPERATIONAL STATUS <u>R</u> Posted for other load-ca <input type="checkbox"/></p> <p>19) BYPASS DETOUR LENGTH <u>3</u> Miles <input type="checkbox"/></p>	<p>POSTED SIGNS</p> <p>+ POSTED VERT. CLR UNDER BRIDGE <u>0</u> ft <u>0</u> in <input type="checkbox"/></p>
--	---

COMMENTS:

Geometric data not verified for Rte 15 at the 2011 supplemental inspection. 105 12/28/11 during

<p>GEOMETRIC DATA</p> <p>+ 10) INV. RTE. MIN. VERT. CLEARANCE <u>14</u> ft <u>5</u> in <input type="checkbox"/></p> <p>+ 47) LOG INV. RTE. TOTAL HORIZ. CLR. <u>228</u> ft <input type="checkbox"/></p> <p>+ 47) RLOG INV. RTE. TOTAL HORIZ. CLR. <u>29.2</u> ft <input type="checkbox"/></p> <p>+ LOG MIN VERT CLR OVER INV ROUTE <u>12</u> ft <u>2</u> in <input type="checkbox"/></p> <p>+ RLOG MIN VERT CLR OVER INV ROUTE <u>12</u> ft <u>10</u> in <input type="checkbox"/></p> <p>+ 55) MIN LAT UNDERCLR ON RIGHT <u>H</u> <u>3</u> ft <input type="checkbox"/></p> <p>+ 56) MIN LAT UNDERCLR ON LEFT <u>1.8</u> ft <input type="checkbox"/></p>

* FILL OUT ON EVERY INSPECTION 29, 109, 30, 41

- VERIFY EVERY INSPECTION 28B, 10, 47, 53, 55, 56 & POSTED VERT CLEARANCE UNDER THE BRIDGE

** MUST BE FILLED OUT OR VERIFIED ON THE FIRST INSPECTION MADE BASED ON THE NEW FHWA GUIDE 102

4/91

Connecticut Department of Transportation

Bridge Inspection Report BRI-18

Bridge #: 00708

Inspection Date: 11/25/2011

Inspection Type:	Routine	Previous Inspection Date:	7/12/2010	Snooper Required:	No
Inspection Performed By:	Others	Feature Carried:	PONUS RIDGE ROAD	Snooper Used:	No
Town:	NEW CANAAN	Feature Intersected:	ROUTE 15	Year Built:	1937
Location:	1.0 MI S OF ROUTE 106	Main Design:	Frame (except frame culverts)	Year Rebuilt:	-
Main Material:	Concrete				

Visits

Visit Date:	Temp:	Start Time:	End Time:	Inspector:	Task:
11/25/2011	60	11:55:00 AM	2:10:00 PM	R. Jantzen	Senior Engineer
11/30/2011	46	10:45:00 AM	12:20:00 PM		
12/23/2011	45	10:05:00 AM	12:15:00 PM		

Inspectors:

DECK:

This is a supplemental inspection done to verify overall ratings. Inspection was limited to ground access and binoculars. Minor elements were not inspected in detail.

Overall Rating:

P

Rating

OVERLAY: 6

Overlay - Concrete paving slabs and bituminous wearing surface over solid concrete frame. Structure has no fill between abutment joints. (See "Additional Notes" below)

Calculated depth of bituminous overlay is 6 IN to 6-1/4 IN. See curb reveal and engineer comments in "Additional Notes".

Bituminous overlay shows transverse and longitudinal cracks at random locations, typically 6 FT to 10 FT in length and hairline to 1/16 IN open.

There are several longitudinal and transverse cracks and one random crack up to 25 FT long and 1/8 IN to 3/16 IN open. These cracks are primarily at the NE corner of the span.

The longitudinal crack along the centerline of roadway extends 3/4 of the way between the abutments.

Many longitudinal cracks coincide with the joints between the paving slabs, located approximately at 5 FT from the curbs and at the centerline.

A 6 IN wide band of braided longitudinal hairline cracks is located 3 FT off the west curb and extends nearly abutment to abutment.

5/41

		<p>A 3 FT wide band of medium raveling runs full length of the curb on both east and west sides.</p> <p>The overall number and density of cracks is high enough at the north end of the span as to create a large interconnected pattern of cracking.</p> <p>A 12 IN diameter bituminous patch is located in the northbound travel lane between the south abutment and mid-span.</p> <p>Along both curbs there is grass growth, heavy at random locations, and a heavy build up of leaves.</p>
DECK-STR. CONDITION:	N	Per CT. BRIDGE INSPECTION MANUAL: When approach paving is carried across the top of the deck there is no deck and overall rating will be "N".
CURBS:	5	<p>Concrete curbs / rail bases-</p> <p>Both curbs show minor hairline cracks and light scale through-out. Many hairline cracks on the inside vertical face extend across the top of curb and down the outside face but do not penetrate into the frame fascias or wing walls.</p> <p>Both curbs show cracks on the inside face that extend across the curb and connect with significant cracks in the frame fascias and wing walls. Widths for these significant cracks on the inside curb face vary, from 0.013 IN up to 1/32 IN at the NE (near A-2) for the east curb, and from 0.20 IN up to 1/8 IN at the NW (near A-2) for the west curb.</p> <p>East curb has several areas of severe scale up to 6 IN high x 5 IN deep (total 19 LF).</p> <p>West curb has an isolated area of severe scale near the south abutment (4 LF x 1 IN deep).</p> <p>Curb reveal at east curb is 6 IN typical. Curb reveal at west curb is typically 5-1/2 IN to 6 IN.</p>
MEDIAN:	N	-
SIDEWALKS:	N	-
PARAPET:	N	-
RAILING:	6	<p>Concrete balustrade type-</p> <p>Railing generally shows minor hairline to slightly open cracks at random locations and extensive areas of light scale.</p> <p>There is a severe scale area at the northeast near A-2 @ 4 FT. long x 6 IN high x 2 IN deep.</p> <p>Heavy vine overgrowth is occurring at all four wing walls. The vine overgrowth extends 5FT to 10 FT out towards midspan at the NE and NW corners, and extends out 35 FT toward midspan at the southeast.</p>
PAINT:	N	-
FENCE:	N	-
DRAINS:	N	-
LIGHTING STANDARD:	N	-
UTILITIES	N	-

6/41

TYPE/SIZE:		
CONSTR JOINTS:	N	The longitudinal construction joint is discussed as part of the frame intrados in the "Superstructure" section below.
EXPANSION JOINTS:	4	<p>There are deck end joints in the concrete curbs / railbases at A-1 and A-2, but there are no formal joints in the bituminous overlay. The transverse joints between the concrete pavement slabs have been paved over at both of those locations.</p> <p>There are full width transverse cracks in the bituminous overlay at both A-1 and A-2 that coincide with the deck end joints in the curbs. The transverse cracks are up to 1 IN open at A-1 (south abutment) and up to 1/2 IN open at A-2 (north abutment).</p> <p>There is grass growing in the transverse crack at A-1, SE corner.</p>

7/41

59.

SUPERSTRUCTURE:

This is a supplemental inspection done to verify overall ratings. Inspection was limited to ground access and binoculars. Minor elements were not inspected in detail.

**Overall
Rating:**

4

Rating**BEARING DEVICES:**

N

-

STRINGERS:

4

Concrete Rigid Frame, Frame Slab Fascias-

The concrete frame is solid. There is no fill or ballast, and therefore, there are no spandrel walls to hold the fill.

Frame fascias exhibit vertical / diagonal cracking with heavy efflorescence in the negative moment tension zones at all four corners (2 cracks @ NW, 2 @ SW, 2 @ SE and 1 @ NE). These cracks are structural in nature and extend into and across the curbs / railbases. See engineer's notes in "Additional Comments".

East fascia at the north end exhibits 39 SF of severe scale (overall dimensions 12 FT long x 4-1/2 FT high x 3 IN to 8 IN deep). The scale area shows heavy active leakage and heavy efflorescence with stalactite candles. Significant efflorescence is building up on the roadway below.

East fascia at the south end exhibits 19.5 SF of severe scale (overall dimensions 10-1/2 FT long x 3-1/2 FT high x 3 IN to 4-1/2 IN deep). The scale area shows active leakage and heavy efflorescence with stalactite candles. Some efflorescence is building up on the roadway below.

West fascia at the mid-span over Rte 15 NB left lane exhibits 5.5 SF of severe scale (overall dimensions 5 FT long x 2 FT high x 3 IN deep).

Frame fascias at NE, SE and SW corners and at west fascia mid-span also exhibit scattered horizontal and diagonal hairline cracks and areas of map hairline cracking adjacent to structural cracks and areas of severe scale.

The east fascia shows heavy vine overgrowth for 35 LF from south leg to midspan.

GIRDERS:

4

Concrete Rigid Frame, Frame Slab-

Frame slab extrados is not visible due to pavement slabs and bituminous overlay. Ratings based on condition of frame slab intrados / soffit.

Frame slab has a full length longitudinal construction joint at the bridge centerline. The joint is in the slab only and does not extend into the frame legs. This construction joint is not indicated in the original plans.

***The longitudinal joint exhibits light to moderate leakage stains and efflorescence for 16 LF near the south leg (A-1).

***The longitudinal joint exhibits heavy leakage stains and heavy efflorescence with stalactite candles for 16 LF near the north leg (A-2).

***The longitudinal joint exhibits leakage stains and 43 SF of spalling with exposed rebar for 30 LF in the mid-span area. Spalls range from 1 FT long x 1/2 FT wide and 1 rebar exposed up to 11 FT long x 1-1/2 FT wide and 4 rebar exposed. Rebar generally shows heavy laminar rust and significant section loss but due to limited access no details are available.

***In some spalls along the joint, the rebar were painted with a protective coating in the past, but the coating is now flaking off in places and rust

8/41

FLOOR BEAMS:

		<p>bleeding through in other locations. In addition, the spalls have now extended beyond the painted area and have exposed extensive new areas of rusted rebar.</p> <p>The frame slab soffit shows 2 isolated spalls: 1 x 1 SF located over Rte 15 NB right lane near the east fascia, and 1 x 1 SF located over Rte 15 SB left lane near the west fascia.</p> <p>The frame slab soffit shows large areas in the mid-span area up to 12 FT long x 18 FT wide of map cracking with dampness and / or efflorescence along the cracks and general stains and discoloration. In some locations there are stalactite candles.</p> <p>The frame slab soffit shows large areas in the mid-span area up to 8 FT long x 9 FT wide of map cracking with dampness but w/o efflorescence along the cracks as well as general stains and discoloration.</p> <p>The frame slab soffit shows one area along the longitudinal joint up to 18 FT long x 2-1/2 FT wide of braided longitudinal cracking with dampness and / or efflorescence along the cracks and general stains and discoloration. In some locations there are stalactite candles.</p> <p>There is an isolated point source of efflorescence and active leakage near the south leg.</p> <p>Total area of spalls is 45 SF. Total area of map cracks with efflorescence and / or dampness is 773 SF. Total deterioration on the frame slab soffit is 818 SF or 31% of total deck area.</p> <p>The frame slab soffit also shows large areas near the south and north legs up to 16 FT long x 16-1/2 FT wide of stains, discoloration and latent (i.e. potential future) map cracks. Total area of discoloration and latent cracks is 824 SF or 31% of overall deck area.</p>
	4	<p>Concrete Rigid Frame, Frame Legs / Stems-</p> <p>The frame legs show scattered vertical and horizontal hairline cracking, some with light efflorescence, and extensive areas of light scale.</p> <p>South frame leg (at Abutment-1) exhibits a full height vertical crack 10 FT high x 0.20 IN open with active leakage and heavy efflorescence. Crack extends from top of brush wall to the center line construction joint of frame slab.</p> <p>North leg shows a full height vertical crack 10.6 FT high x 1/8 IN open with very heavy active leakage and heavy efflorescence. Crack extends from top of brush wall to the center line construction joint of frame slab.</p> <p>North leg shows two areas of severe scale along the open vertical crack: ***One area @ 12 IN high x 7 IN x 2 IN deep at the top of crack adjacent to the frame slab ***Other area @ 9 FT high x 7 IN wide x 6 IN deep adjacent to the top of the brush wall.</p> <p>North frame leg in the larger area of severe scale has a vertical rebar exposed 4 FT high with heavy laminar rust and section loss. The exposed rebar shows 38% section loss with 11/16 IN diameter remaining of original 7/8 IN diameter.</p> <p>North frame leg, east end face shows a horizontal hairline crack 18 IN long located 2 FT below the springline.</p>
TRUSSES-GENERAL:	N	-
TRUSSES-PORTALS:	N	-

9/41

TRUSSES- BRACING:	N	-
PAINT:	N	-
RUST:	N	-
MACHINERY MOV SPAN:	N	-
RIVETS & BOLTS:	N	-
WELDS - CRACKS:	N	-
TIMBER DECAY:	N	-
CONCRETE CRACKING:	4	See comments under "Stringers", "Girders" and "Floorbeams" above.
COLLISION DAMAGE:	7	Area of scrapes 6 FT long x 12 FT wide is located over the northbound right travel lane (SE corner).
MEMBER ALIGNMENT:	8	-
DEFLECT. UNDER LOAD:	N	Normal.
VIBRATION UNDER LOAD:	N	Normal.
STAND PIPES:	N	-
BARREL LADDERS:	N	-

ARE BARREL LADDERS OSHA COMPLIANT? -

60.

SUBSTRUCTURE:

This is a supplemental inspection done to verify overall ratings. Inspection was limited to ground access and binoculars. Minor elements were not inspected in detail.

Overall Rating:

6

Rating

ABUTMENTS- STEM:	N	Concrete rigid frames have no abutments as such. The frame legs take distributed moments from live loads and are considered part of the superstructure. See comments under "Floorbeams" above.
ABUTMENTS- BACKWALL:	6	<p>No backwalls.</p> <p>Concrete jersey shaped brush walls- The brush walls are not part of original construction and are non-structural.</p> <p>The south brush wall (at base of south leg) has 9 full height vertical hairline cracks and 1 partial height hairline crack. Some cracks exhibit efflorescence.</p> <p>The south brush wall has a small corner spall 4 IN long x 4 IN wide x 3 IN deep at the east end.</p> <p>The south brush wall has a large spall 5 IN long x 12 IN high x 3/4 IN deep with an adjacent horizontal crack 5 IN long x 1/32 IN open located near the east end.</p> <p>The north brush wall (at base of north leg) has 7 full height vertical hairline cracks and 2 partial height hairline cracks.</p>

10/41

ABUTMENTS- FOOTINGS:	N	Not visible.
ABUTMENTS- SETTLEMENT:	8	No indications of settlement noted.
ABUTMENTS- WINGWALLS:	6	<p>Concrete wing walls and corner pylons-</p> <p>All wing walls and pylons show areas of light scale.</p> <p>All wing walls show heavy vine overgrowth limiting observation. In addition, access to wing walls is limited by heavy growth of brambles, briars and brush.</p> <p>NW wing wall exhibits a vertical crack, full height x 1/32 IN open, with heavy efflorescence. The crack extends into and across the curb / railbase. There is also an adjacent horizontal hairline crack with efflorescence on the outside face of the railbase.</p> <p>The NW pylon shows 2 vertical hairline cracks x 12 IN high at the base (one with efflorescence), and 2 horizontal hairline cracks x 24 IN long in lower half of the pylon.</p> <p>The NW pylon has 1 horizontal hairline crack x 18 IN long with heavy efflorescence and a large adjacent spall 4 IN long x 10 IN high x 1 IN deep located in lower half of the pylon.</p> <p>The NW pylon also has a horizontal construction defect 18 IN long in lower half of the pylon. The defect is not a crack.</p> <p>The SW wing wall has a full height vertical / diagonal hairline crack. The crack extends into and across the curb / railbase.</p> <p>The SW wing has a vertical crack, full height x 1/16 IN open, with efflorescence and a large adjacent spall 7 IN long x 12 IN high x 2 IN deep. The crack extends into and across the curb / railbase.</p> <p>The SW wing shows a spall with exposed rebar, 3 IN long x 6 IN high x 3/4 IN deep. The rebar was painted with a protective coating in the past but the coating has failed and the rebar is heavily rusted.</p> <p>The SE wing wall has 1 vertical hairline crack x 30 IN high and 1 vertical hairline crack x 8 FT high.</p> <p>The NE wing wall shows has 1 vertical hairline crack x 6 FT high and 1 nearby vertical hairline crack x 12 IN high.</p> <p>The NE wing wall has a large spall, 9 IN long x 12 IN high x 2 IN deep, with active leakage and heavy efflorescence.</p>
PIERS/BENTS- CAPS:	N	-
PIERS/BENTS-PILE BENT:	N	-
PIERS/BENTS- COLUMNS:	N	-
PIERS/BENTS- FOOTING:	N	-
PIERS/BENTS- SETTLMT:	N	-
EROSION-SCOUR:		

11/41

	N	-
CONCRETE CRACK-SPALL:	7	See above comments.
STEEL CORROSION:	N	-
PAINT:	N	-
TIMBER DECAY:	N	-
COLLISION DAMAGE:	8	-
DEBRIS:	N	-

61. CHANNEL &
CHANNEL
PROTECTION:

Overall Rating:

62. CULVERTS &
RETAINING
WALL:

Overall Rating:

65. APPROACH
CONDITION

This is a supplemental inspection done to verify overall ratings. Inspection was limited to ground access and binoculars. Minor elements were not inspected in detail.

Overall Rating:

Rating

APPROACH SLAB:

5

Concrete approach slab-
Approach slab is paved over. The approach slab is considered to occupy the space between the wing wall curbs and railings. The slab appears to have same configuration as the concrete pavement over the bridge w/ 2 x 10 FT wide travel lane slabs and 2 x 5 FT wide shoulder slabs. Ratings are based on condition of the bituminous overlay.

South approach slab-
***South approach slab overlay shows several longitudinal cracks up to 15 FT long x 1/4 IN open. These cracks roughly coincide with the joints between the concrete pavement slabs at 5 FT from the curbs.

***Overlay also shows several short (3 FT to 5 FT long) transverse cracks open 1/16 IN to 1/4 IN that intersect the longitudinal cracks.

***At the SW corner (near A-1) the approach overlay exhibits a random crack approximately 15 FT long x 1/2 IN open.

***Near the south end of the wing wall railings there is a full width transverse crack up to 1 IN open.

***At the south end of the SW wing wall railing there is a transverse crack 15

12/41

		<p>FT long x 1 IN open.</p> <p>***A 3 FT wide band of medium raveling runs full length of the curb on both east and west sides</p> <p>North approach slab-</p> <p>***North approach slab overlay shows several longitudinal cracks up to 30 FT long x 1/4 IN open. Most of these cracks coincide with the joints between the concrete pavement slabs at 5 FT from the curbs.</p> <p>***There are several short transverse cracks open 1/16 In to 1/8 IN across the roadway centerline.</p> <p>***There is a single transverse crack near the north end of the NE wing railing that is 5 Ft long x 1/4 IN wide.</p> <p>***A 3 FT wide band of medium raveling runs full length of the curb on both east and west sides.</p>
RELIEF JOINTS:	N	-
APPROACH GUIDE RAIL:	3	<p>Single wood post only at both NE and NW ends of railings.</p> <p>SE end has multiple wood posts drilled for 2-WRR but only one cable is present. Cable detached from the post closest to the bridge and is completely slack. Several posts are missing.</p> <p>SW end has multiple wood posts drilled for 2-WRR but no cable is present.</p>
APPROACH PAVEMENT:	6	The bituminous pavement for the approach beyond the wing wall railings shows transverse and longitudinal cracks at random locations up to 1/4 IN open at both north and south approaches.
APPROACH EMBANKMENT:	8	Embankments are well vegetated and stable.

TRAFFIC SAFETY FEATURES

Rating

BRIDGE RAILINGS:	<p>Last Inspection: 0</p> <p>Current: 0</p>	Concrete balustrade railings are un-modified and do not meet current standards.
TRANSITIONS:	<p>Last Inspection: 0</p> <p>Current: 0</p>	<p>Approach guide rail is not attached to the bridge.</p> <p>Also curbs project out, presenting a blunt end to traffic.</p>
APPROACH GUARDRAILS:	<p>Last Inspection: 0</p> <p>Current: 0</p>	The 2-WRR guiderail with wood posts does not meet current standards.
APPR. GUARDRAIL ENDS:	<p>Last Inspection: 0</p> <p>Current: 0</p>	Insufficient flare at ends.

13/41

66. LOAD POSTING

- Posted Loading -

SINGLE UNIT (TONS):	Last Inspection: - Current: -	-
SEMI TRAILER (TONS):	Last Inspection: - Current: -	-
4 AXLE (TONS):	Last Inspection: - Current: -	-
3S2 (TONS):	Last Inspection: - Current: -	-
ADVANCE WARNING (Y/N):	-	-
LEGIBILITY:	-	-
VISIBILITY/LOCATION:	-	-

67. MISCELLANEOUS

Rating

MIN. VERT. UNDERCLEARANCE:	Last Inspection: 12' 8" Current: -' -"	Min.Vert. Clr. Southbound 12ft. - 8in. Not verified at the 2011 supplemental inspection.
POSTED CLR. UNDER BRIDGE:	Last Inspection: -' -" Current: -' -"	-
POSTED CLR. ON BRIDGE:	Last Inspection: -' -" Current: -' -"	-
ADVANCED WARNING (YES/NO):	No	-
SPEED LIMIT (IF ANY):	Last Inspection: 25 Current: -	-
CHARACTER OF TRAFIC:	Moderate volume, mostly automobiles and a few trucks.	

ADDITIONAL NOTES:

Engineer Notes:

The concrete pavement slabs on the bridge consist of two 10 FT wide slabs, one on either side of the centerline (travel lane pavement slabs), and two 5 FT wide slabs, one along each curb (shoulder pavement slabs).

14/41

The pavement slabs vary in thickness from 6-5/8 IN at the curb line to 7-1/2 IN at the centerline. The original curb reveal for bare concrete pavement slabs was 12 IN.

The vertical / diagonal cracks noted in the frame slab fascias at the corners are typical for the concrete rigid frames constructed along the Merritt Parkway in the 1930's. Although the plans indicate that the very heavy reinforcing steel (#7 to #9 rebar) was intended to extend across the full width of the structure, investigations at other bridges have found that smaller #4 to #5 rebar were substituted under the curbs and railings. The smaller rebar are unable to resist the stresses applied and cracking results. Although structural in nature, these cracks do not indicate a problem with the load capacity of the structure unless the cracks extend into the area of heavy reinforcement. This would be indicated on this structure by the fascia cracks propagating down to the soffit and connecting with transverse cracks that extend more than 2 FT from the soffit edge.

**ADDITIONAL
COMMENTS:**

Merritt Parkway (Rte 15) is logged south to north. The highway crosses under the structure SW to NE.

Ponus Ridge Road is the structure inventory route and is logged south to north.

Bridge was inspected south to north with south frame leg (Frame stem #1) / south abutment (A-1) lies along Rte 15 northbound and the west fascia is closest to New York state (i.e. in direction of Rte 15 SB). This is in agreement with plans and the previous inspections.

Verified in field during 2011 inspection overall structure length and out-to-out measurements. From paving notch-to-paving notch (measured at joints in curbs since roadway joints paved over) the overall length is 73.7 FT which is in accordance with plans (coded Item 49 as 74 FT). The out-to-out measurement was confirmed as 35.5 FT which is slightly wider than the plans.

Inspectors' Signatures:

1)



Date: 12/28/2011

2)

Date: ---/---/---

3)

Date: ---/---/---

4)

Date: ---/---/---

P.E. Signature:



Date: ---/---/---

P.E. #:

Date: ---/---/---

15/41

Reviewed by:


Ronald Janty conndot

Date: 12/28/2011

BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE Deterioration of Frame Intrados (Slab Underside)			SHEET NO. 1 of 6 <i>16/41</i>
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team

- Legend:
- = Condition 1 (Stains & Discoloration, plus latent / potential future cracks)
 - = Condition 2 (Condition 1 plus Joint leakage stains)
 - = Condition 3 (Mapcracks with dampness along cracks, plus stains & discoloration)
 - = Condition 4 (Mapcracks with dampness and efflo, plus stains & discoloration)
 - = Spall with exposed rebar
 - = Spall w/o rebar

North



Approx. Scale:

= 2 FT x 2 FT

BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE Intrados (slab soffit) Deterioration Calculations			SHEET NO. 2 of 6 17/41
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team

Overall Deck Area = out-out x overall length = 35.5' x 74' = 2627 SF

Area of Intrados (slab soffit) = width of intrados x clear span = 34.2' x 65' = 2223 SF

Areas of Deterioration :

Spalls (100% area) -

1' x 1/2' = 1/2 SF
 1' x 1' = 1 SF
 1' x 1' = 1 SF
 4' x 1' = 4 SF
 5' x 1' = 5 SF
 5' x 1' = 5 SF
 11' x 1-1/2' = 16-1/2 SF
 12' x 1' = 12 SF

Total SF spalls = 45 SF

Areas of Discoloration, Stains, and Latent (potential future) mapcracks :

2' x 4' = 8 SF
 4' x 4' = 16 SF
 10' x 1-1/2' = 15 SF
 10' x 7' = 70 SF
 10' x 16-1/2' = 165 SF
 16' x 1-1/2' = 24 sf
 16' x 1-1/2' = 24 SF
 16' x 3' = 48 SF
 16' x 16-1/2' = 264 SF
 (18' x 2') - (5' x 1') - (4' x 1') = 27 SF
 (18' x 10') - (5' x 1') - (12' x 1') = 163 SF

Total SF discoloration, stains, latent mapcracks = 824 SF

Map cracks w/ dampness and / or efflo (100% area) -

1/4 SF (point source of efflo) = 1/4 SF
 8' x 8' = 64 SF
 8' x 9' = 72 SF
 11' x 16' = 176 SF
 14' x 15-1/2' = 217 SF
 (18' x 2-1/2') - (1' x 1/2' spall) = 44-1/2 SF
 (18' x 12') - (11' x 1/2' spall) = 199-1/2 SF
 Total SF mapcrack, efflo = 773-1/4 SF

Percentage stains of overall deck area = 824 SF / 2627 SF = 31.4 %


(Percentage of intrados area = 824 SF / 2223 SF = 37.1 %)

Total deterioration (spalls and mapcracks) = 45 SF + 773.25 SF = 818.25 SF

Percentage deterioration of overall deck area = 818.25 SF / 2627 SF = 31.1 %


(Percentage of intrados area = 818.25 SF / 2223 SF = 36.8 %)

BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE Deterioration on Frame Fascias			SHEET NO. 3 of 6 18/41
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team



Note - Crack widths are measured at the top of the outside edge of the curb / railbase. See callout on Sheet 4, South abutment sketch.

All cracks shown extending into the curb / railbase extend across the curb and down the inside face.





Total of 19.5 severe scale at SE corner.

Total of 39 SF severe scale at NE corner.

Note - Crack widths are measured at the top of the outside edge of the curb / railbase. See callout on Sheet 4, South abutment sketch.

All cracks shown extending into the curb / railbase extend across the curb and down the inside face.



BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE Deterioration at Abutments / Frame legs			SHEET NO. 4 of 6 19/41
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team



* Scale has exposed one vertical rebar approx 8' high, with heavy laminar rust and section loss.



Exposed rebar shows 11/16" dia. remaining of 7/8" dia. original (38% section loss)

BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE Deterioration of Wing Walls and Pylons			SHEET NO. 5 of 6 20/41
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team



Scale:


= 3 FT horiz x 3 FT vert



General notes -


1. All wing walls and pylons show large areas of light scale.
2. All wingwalls show heavy vine growth limiting ability to see areas of deterioration. Access to all wings is limited by heavy growth of vines, brambles and brush immediately adjacent to wing walls.
3. All full height cracks extend across the top of the curb / railbase and down the inside face of the curb.

BRIDGE NO: 00708	TOWN: New Canaan	ROUTE/STREET: Ponus Ridge Road	DATE PREPARED: 11/25/11
UNIT NO: 1307	TEAM NO: Field Engr	OVER ROUTE/STREET: Route 15	PREPARED BY: R Jantzen
DRAWING TYPE: Deterioration of Overlay			SHEET NO. 6 of 6 2/1/11
Revision	1	Date	Team
	2	Date	Team
	3	Date	Team
	4	Date	Team



BR 00708, Ponus Ridge Rd o/ Route 15, New Canaan

12/23/2011

Estimated ADT for 2011 Using 2008 Hard Count

2008 ADT
COUNTED: MAR/APR
NEW CANAAN
CONNECTICUT

BR 00708, Ponus Ridge Rd o/ Route 15, New Canaan

12/23/2011

Estimated ADT for 2011 Using 2008 Hard Count



Calculations for 2011 Estimated ADT

Road classification is "Urban Minor Arterial", use growth rate of 1.1 per 10 years.

Hard count 2008 ADT = 2700

Estimated 2011 ADT = $2700 \times 1.03 = 2781$; therefore use **2780** as estimated 2011 ADT

Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



Description 1: Looking across bridge from south approach.



Description 2: Transverse crack in overlay at south deck / frame edge. Crack aligns with joint in curb / railbase.



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection




<p>Description 3: Typical overlay condition on bridge showing large pattern mapcracking and random longitudinal and transverse cracks. Shoulder area shows braided longitudinal cracks and moderate raveling. SB lane shown.</p>	<p>Description 4: Transverse crack in overlay at north deck / frame end. Crack aligns with joint in curb / railbase.</p>




Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection

	
<p>Description 5: Looking across bridge from north approach.</p>	<p>Description 6: West elevation showing cracking of fascia at NW and SW corners and severe scale over left lane of NB Rte 15.</p>


Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection




<p>Description 7: Close up of 1/16" open crack of fascia at NW corner (negative moment area).</p>	<p>Description 8: Close up of severe scale on fascia (5.5 SF x 3" deep) near midspan.</p>



Bridge No.	00708	Inspected by:	R. Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection






Description 9: Close up of cracking of fascia at the SW corner (cracks open 0.40" to 1/16").



Description 10: East elevation showing large areas of severe scale on fascia at NE and SE corners.



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection




	
<p>Description 11: Close up of severe scale on fascia at SE corner. Total 19.5 SF x 4.5" deep.</p>	<p>Description 12: Close up of severe scale on fascia at NE corner. Total 39 SF x 8" deep.</p>



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



	
<p>Description 13: Close up of severe scale on fascia at NE corner. Total 39 SF x 8" deep.</p>	<p>Description 14: Close up of severe scale on fascia at NE corner. Note active leakage and very heavy efflorescence at area of deepest scale.</p>

Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



		<p>Description 15: South frame leg showing vertical crack (0.20" open) with heavy efflorescence and south end of frame slab soffit with heavy spalling and exposed rebars along longitudinal construction joint.</p>	<p>Description 16: Southeast corner of frame intrados showing area of scrapes and isolated spall. Also note staining and efflorescence on either side of longitudinal construction joint.</p>
--	---	---	--





Bridge No.	00708	Inspected by:	R. Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection


<p>Description 17: General view of north frame leg and frame intrados (slab soffit). Note heavy spalling and exposed rebar along longitudinal joint in intrados and large crack (1/8" open) with associated scale up to 7" wide at north leg.</p>	<p>Description 18: West side of intrados showing areas of mapcracking with dampness.</p>



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection




		<p>Description 19: East side of intrados showing areas of mapcracking with dampness.</p>	<p>Description 20: Close up of mapcracking in Photo 20 (near tip of arrow).</p>
--	---	---	--

Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection




	<p>Description 21: View of spalls with exposed rebar along longitudinal joint over NB lanes. Note some rebar previously coated with protective sealer.</p>
	<p>Description 22: View of spalls with exposed rebar along longitudinal joint over SB lanes.</p>





Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection

<p>Description 23: View of intrados adjacent to north leg shows areas of discoloration, stains and latent mapcracks.</p>	<p>Description 24: View of longitudinal joint from north leg showing heavy efflorescence and adjacent area of braided longitudinal cracks with dampness. Also note extensive spalling and exposed rebar.</p>



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection

	
<p>Description 25: NE corner of intrados showing area of discoloration stains and latent mapcracks near north leg and area of mapcracking with dampness near midspan.</p>	<p>Description 26: NE corner of intrados showing area of discoloration stains and latent mapcracks near north leg.</p>





Bridge No.	00708	Inspected by:	R. Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection


<p>Description 27: West side of intrados showing isolated spall and area of mapcracking with dampness over SB lanes.</p>	<p>Description 28: NW corner of intrados showing area of discoloration stains and latent mapcracks near north leg.</p>





Bridge No.	00708	Inspected by:	R. Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	11-25-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection

	
<p>Description 29: North leg of frame showing large crack (1/8" open) with associated scale up to 7" wide x 6" deep. Heavy active leakage at crack is running down over brush wall at leg base.</p>	<p>Description 30: North leg showing large crack (1/8" open) with associated scale up to 7" wide x 6" deep. Exposed vertical rebar shows severe rust with 38% section loss. Crack shows heavy active leakage and efflorescence.</p>



Bridge No.	00708	Inspected by:	R. Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	12-23-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



	
<p>Description 1: SW wing wall showing vertical cracks and spall with exposed rebar.</p>	<p>Description 3: SE wing wall showing an 8 FT and a 30 IN vertical hairline cracks.</p>

Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	12-23-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



	
<p>Description 4: NW wing wall showing full height vertical crack open 1/32 IN.</p>	<p>Description 9: NW corner pylon showing horizontal and vertical hairline cracks. Note hairline crack with heavy efflorescence and adjacent spall at right side of photo. Also note construction defect (not a crack) at left side of photo.</p>



Bridge No.	00708	Inspected by:	R Jantzen
Town:	New Canaan	Inspected by:	
Feature Carried:	Ponus Ridge Road	Date Inspected:	12-23-2011
Feature Crossed:	Route 15	Project No.:	Supplemental Inspection



Description 10: NE wing wall showing vertical hairline cracks and large spall with efflorescence and active leakage.



Description 21: Heavy cracking of overlay at NE quadrant of bridge span. Cracks up to 3/16 IN open.